

# TECHNICAL INFORMATION HOTSTRIP

# 1. <u>INTRODUCTION</u>

**Hotstrip** is a heavy duty caustic paint stripper and rust remover. **Hotstrip** is formulated to remove paint from steel and other caustic resistant surfaces. **Hotstrip** is formulated to break the various linkages which hold the paint film together, resulting in the complete breakdown of the dried paint and its removal from the substrate. In rust removal applications, it is used at boiling point. Time will depend on degree of rusting.

# 2. OPERATION SUMMARY

**CONCENTRATION** 20 – 30 % W/V(200 – 300 g/Litre)

**TEMPERATURE** 80°C to rolling boil

**TIME** 30 minutes to several hours

METHODImmersionEQUIPMENTMild steel tank

We recommend conducting a trial to ensure that **Hotstrip** removes the required paint and establish optimum conditions. Metal parts should be thoroughly rinsed in water after the paint is removed. When a new bath is made, add 30 kg of **Hotstrip** to 100 litres of cold water. Add the product in small quantities at a time, preferably while stirring the bath. **NEVER ADD TO VERY HOT OR BOILING SOLUTION!** 

# 3. BATH CONTROL

The bath is controlled by means of a simple titration as follows:

- **A.** Take a 5 ml sample from the bath to be tested and dilute to 100 ml with water.
- **B.** Take a 10 ml sample of the solution prepared in 1. Make up to 100 ml in water.
- **C.** Add 5 drops phenolphthalein indicator.
- **D.** Titrate with 0.1 N H<sub>2</sub>SO<sub>4</sub> until pink colour disappears.

Concentration **Hotstrip** (g/L) = number of mls x 17.

### 4. PRECAUTIONARY INFORMATION

**Hotstrip** is a highly alkaline material containing potassium hydroxide. When handling, wear goggles or face shield and rubber gloves.

When **Hotstrip** is added to a working bath or when a new bath is made, the temperature of the solution increases. Take precautions to avoid splashes.

HOTSTRIP Page 2

# 5. FIRST AID

SKIN If contact occurs, remove contaminated clothing and wash affected

area thoroughly.

EYES Hold eyelids open and flush with water for at least 15 mins. Get

medical advice without delay.

INGESTED Rinse mouth. If swallowed DO NOT induce vomiting. Give a glass of

water. Get medical advice without delay.

INHALATION If fume inhaled, remove patient to fresh air, lay down, rest, keep warm.

If patient is not breathing, make sure airway is clear and apply artificial respiration. Oxygen may be given out only under supervision of a

trained person. Transport to a hospital or doctor.

#### 6. PACKAGING

Hotstrip is packed in 25 kg bags.

#### **DISCLAIMER**

Any information given is, to the best of our knowledge, the best currently available, with respect to our products and their use, but it is subject to revision as additional knowledge and experience is gained. Such information is offered as a guideline for experimentation only and is not to be construed as a representation that the material is suitable for any particular purpose or use. Customers are encouraged to make their own enquiries as to the material's characteristics and, where appropriate, to conduct their own tests in the specific context of the material's intended use. This information is not a license to operate under nor is it intended to suggest infringement of any patent. We guarantee a uniform quality standard for this product. The only conditions and warranties accepted by Henkel in relation to this product or process are those implied by either Commonwealth or State statutes.

Ref: HOTSTRIP/AR/SJG Issue Date : 26<sup>th</sup> June 2000

Page 2 of 2